CAR CARE CENTER (BUILDING 1568) TU-24

Joint Base Andrews

February 2013

BACKGROUND

The Car Care Center, TU-24 (formerly known as AOC-24) is located on F Street near the Main Gate of Joint Base Andrews (JBA). From approximately 1953, the Car Care Center operated as a gas station with three service bays and two fuel islands. The fuel islands were removed in 1980. The Car Care Center is currently an Army and Air Force Exchange Service (AAFES) automobile maintenance and repair shop.

In the early 1980s, the three 10,000-gallon underground storage tanks (USTs) were pumped dry and abandoned inplace by filling them with sand. Two waste oil USTs and a fuel oil UST were removed circa 1986 and replaced with an above-ground storage tank (AST). A geophysical survey performed in 2003 indicated the presence of seven additional 1950s-era USTs adjacent to the building.

RISK DRIVERS

<u>Contaminants:</u> Petroleum constituents <u>Media:</u> Groundwater and subsurface soil <u>Exposure Pathways Completed:</u> Construction worker exposure during excavation <u>Drainage:</u> Meetinghouse Branch <u>Current Land Use/Surface Cover:</u> Industrial <u>Reasonably Anticipated Land Use:</u> Industrial

Relative Risk: NR

CHALLENGES

The investigation and remedy have been completed and the site is closed.

PERFORMANCE BASED APPROACH

The identified USTs and the contaminated soils associated with the tanks were removed from the site between 2004 and 2005. Over 2,248 tons of petroleum-impacted soil was excavated from the site as well as thousands of gallons of petroleum-impacted groundwater. Oxygen Release Compound (ORC) was placed in the excavations prior to backfilling and injections of ORC also occurred down gradient of the excavations.



Figure 1: TU-24 Site Map (Source: URS 2005)

ORC stimulates the naturally occurring microbial communities in the soil which consume petroleum constituents. Groundwater monitoring at the site displayed a steady decline in contaminant levels.

The interim remedial action at site TU-24 was successful and Remedy in Place (RIP) was achieved in 2007. This site is closed and groundwater monitoring wells were properly abandoned. One well, MW04-1568, remains at the site as part of the basewide groundwater monitoring well network.

The past schedule for this site was:	
The past selfedule for this site was.	
Remedial Investigation (RI)	4/2007 (Complete)
Feasibility Study (FS)	4/2007 (Complete)
Proposed Plan (PP)	4/2007 (Complete)
Record of Decision (ROD)	4/2007 (Complete)
Remedial Design (RD)	N/A
Remedial Action-Construction (RA-C)	4/2007 (Complete)
Remedy in Place (RIP)	4/2007 (Complete)
Remedial Action-Operation (RA-O)	N/A
Response Complete (RC)	4/2007 (Complete)
Site Closure (SC)	9/2011 (Complete)