

# DAVIDSONVILLE DUMPING AREA

## AOC-28

Joint Base Andrews/Davidsonville Transmitter Station

April 2022

### BACKGROUND

The Davidsonville Dumping Area (AOC-28) is located approximately 2,000 feet east of the western Davidsonville Transmitter Site boundary and is accessible by the public. Several piles of miscellaneous debris (scrap metal, wood, construction debris, and domestic rubbish) were disposed of at the site between 1986 and 1990. No evidence of dumping hazardous household or industrial materials was observed. General removal of the trash and debris was recommended.

A Preliminary Assessment/Site Investigation (PA/SI) was completed in 2005 to determine whether environmental impacts exist at the site. The PA/SI report recommended no further action at AOC-28. Civil Engineering performed a removal of surface debris in July 2005, and a no further action memorandum was issued in August 2005.

The past schedule for this site was:

Remedial Investigation (RI)	8/2005 (Complete)
Feasibility Study (FS)	8/2005 (Complete)
Proposed Plan (PP)	N/A
Record of Decision (ROD)	N/A
Remedial Design (RD)	N/A
Remedial Action-Construction (RA-C)	N/A
Remedy in Place (RIP)	8/2005 (Complete)
Remedial Action-Operation (RA-O)	N/A
Response Complete (RC)	N/A
Site Closure (SC)	N/A

### CHALLENGES

The investigation and cleanup of the site have been completed.




Figure 1: AOC-28 Site Location Map (Source: URS 2003)

### PERFORMANCE-BASED APPROACH

A Triad site investigation was utilized in 2005 to determine the extent of impacts at this site. The investigation concluded that there is no contamination requiring further investigation or a remedial action. However, a removal of the surface debris was performed.

#### RISK DRIVERS

**Contaminants:** Waste material

**Media:** None

**Exposure Pathways Completed:** Source removed

**Current Land Use/Surface Cover:** Open Space

**Reasonably Anticipated Land Use:** Open Space

**Relative Risk:** NR